

This illustration shows documented seam damage caused by improper installation of a bar system that utilizes round tip set screws.

